

March 23, 2011

**APPROVE THE AWARD OF CONSTRUCTION CONTRACTS AND APPROVE CHANGES TO
CONSTRUCTION CONTRACTS FOR THE BOARD OF EDUCATION'S CAPITAL IMPROVEMENT
PROGRAM**

THE CHIEF EXECUTIVE OFFICER REPORTS THE FOLLOWING DECISION:

Approve the award of Capital Improvement Program construction contracts in the total amount of \$0 to the respective lowest responsible bidders for various construction projects, as listed in Appendix A of this report. These construction contracts shall be for projects approved as part of the Board's Capital Improvement Program. Work involves all labor, material and equipment required to construct new schools, additions, and annexes, or to renovate existing facilities, all as called for in the plans and specifications for the respective projects. Proposals, schedules of bids, and other supporting documents are on file in the Department of Operations. These contracts have been awarded in accordance with section 7-3 of the Rules of the Board of Education of the City of Chicago.

Approve changes to existing Capital Improvement Program construction contracts, in the amount of \$398,403 as listed in Appendix B of this report. These construction contract changes have been processed and are being submitted to the Board for approval in accordance with section 7-15 of the Rules of the Board of Education of the City of Chicago.

Approve changes to existing Capital Improvement Program construction contracts, in the amount of \$632,484 listed in Appendix C of this report. These construction contract changes are being submitted to the Board for approval prior to processing in accordance with section 7-15 of the Rules of the Board of Education of the City of Chicago, since they require an increased commitment in excess of \$50,000 or 10% of the original contract amount, whichever is less, or, as provided under Section 7-5 of the Rules, are necessitated by an unforeseen combination of circumstances or conditions calling for immediate action to protect Board property or to prevent interference with school sessions.

LSC REVIEW: Local School Council approval is not applicable to this report.

AFFIRMATIVE ACTION: The General Contracting Services Agreements entered into by each of the pre-qualified general contractors and other miscellaneous construction contracts awarded outside the pre-qualified general contractor program for new construction awards and changes to existing construction contracts shall be subject to the Board's Business Diversity Program for Construction Projects and any revisions or amendments to that policy that may be adopted during the term of any such contract.

FINANCIAL: Expenditures involved in the Capital Improvement Program are charged to the Department of Operations, Capital Improvement Program.

Budget classification: Fund – 436, 468, 476, 477, 479, 480, 481, 482 will be used for all Change Orders (Appendix B & C); Funding source for new contracts is so indicated on Appendix A

Funding Source: Capital Funding

GENERAL CONDITIONS:

Inspector General – Each party to the agreement shall acknowledge that, in accordance with 105 ILCS 5/34-13.1, the Inspector General of the Chicago Board of Education has the authority to conduct certain investigations and that the Inspector General shall have access to all information and personnel necessary to conduct those investigations.

Conflicts – The agreement shall not be legally binding on the Board if entered into in violation of the provisions of 105 ILCS 5/34-21.3 which restricts the employment of, or the letting of contracts to, former Board members during the one year period following expiration or other termination of their terms of office.

Indebtedness – The Board's Indebtedness Policy adopted June 26, 1996 (96-0626-PO3), as amended from time to time, shall be incorporated into and made a part of the agreement.

Ethics – The Board's Ethics Code adopted June 23, 2004 (04-0623-PO4), as amended from time to time, shall be incorporated into and made a part of the agreement.


Contingent Liability – The agreement shall contain the clause that any expenditure beyond the current fiscal year is deemed a contingent liability, subject to appropriation in the subsequent fiscal year budget(s).

Approved for Consideration:




Opal L. Walls
Chief Purchasing Officer

Approved:




Terry Mazany
Chief Executive Officer

Within Appropriation:



Diana S. Ferguson
Chief Financial Officer

Approved as to legal form:


Patrick J. Rocks
General Counsel

Appendix A

11-0323-PR6

ANTICIPATED
COMPLETE

REG. SCHOOL	CONTRACTOR	WORK DESCRIPTION	CONTRACT AWARD	AWARD DATE	FISCAL YEAR	PROJECT COMPLETE	CAP BUDGET FUND CONTRACT #	PROJECT SCOPE AND NOTES
1 N/A		\$ -	\$ -					
2 N/A		\$ -	\$ -					
3 N/A		\$ -	\$ -					
4 N/A		\$ -	\$ -					
5 N/A		\$ -	\$ -					
6 N/A		\$ -	\$ -					
	All Work Total:	\$ -	\$ -					

REG.	SCHOOL	Affirmative Action			
		AA	H	A	WBE
1	N/A				
2	N/A				
3	N/A				
4	N/A				
5	N/A				
6	N/A				

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Under \$50,000 and 10% (Cumulatively)**

APPENDIX B

11-0323-PR6

21/11/2011

School	Project Num.	Contract Num.	Board Report REG	Type	GENERAL CONTRACTOR ARCHITECT OF REC. Inc.	COR# CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	TOT % OF TIME EXTN
Bogan Technical High School	2010-46041-PLS	2007879	10-0922-PR8	5	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	10	\$633	(\$10,680)	\$765,000	\$774,973	-1.28% 0
Description >> Relocate existing Fire Alarm pull station											
Reason >> Existing Fire Alarm pull station needs to be relocated due to the widening of the door opening											
Justification >> Error/Omission (AOR)											
Bogan Technical High School	2010-46041-PLS	2007879	10-0922-PR8	5	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	3	\$16,240	(\$10,680)	\$785,000	\$790,560	0.71% 0
Description >> Provide epoxy finish on boys' and girls' locker room floors.											
Reason >> Epoxy required by IDPH but alternate for epoxy was not bid per DM direction. Contract includes sealing concrete floors.											
Justification >> Error/Omission (DM)											
Carver Military Academy	2010-46381-PLS	2007911	10-0922-PR8	6	GC Miller	10	\$4,684	\$25,463	\$589,000	\$619,157	5.12% 0
Description >> Furnish and install the starter for the filtration pump											
Reason >> no starter was called for in the equipment list for the filtration pump.											
Justification >> Error/Omission (AOR)											
Carver Military Academy	2010-46381-PLS	2007911	10-0922-PR8	6	GC Miller	2-3	\$5,399	\$25,463	\$589,000	\$619,861	5.24% 0
Description >> Revisions to frame details.											
Reason >> Per permit review revisions.											
Justification >> Permit Review											
Carver Military Academy	2010-46381-PLS	2007911	10-0922-PR8	6	GC Miller	Electric	\$10,261	\$25,463	\$589,000	\$624,723	6.07% 0
Description >> Additional lights and exit signs; feeders; bond all metal parts of pool equipment and motors and add (1) grounding for filtration pump											
Reason >> Per permit review revisions.											
Justification >> Permit Review											
Carver Military Academy	2010-46381-PLS	2007911	10-0922-PR8	6	GC Miller	3-4	(\$1,200)	\$25,463	\$589,000	\$613,263	4.12% 0
Description >> CREDIT: Sealant work at underside of gutter along pool wall joint.											
Reason >> Credit for caulking at perimeter as it is grout.											
Justification >> Error/Omission (AOR)											
Carver Military Academy	2010-46381-PLS	2007911	10-0922-PR8	6	GC Miller	8	\$4,337	\$25,463	\$589,000	\$618,900	5.06% 0
Description >> Per IDPH revisions, install new 3" float valve on fresh water fill pipe at new fill tank; extend fill pipe and provide fresh water fill butterfly valve											
Reason >> Per IDPH review comments											
Justification >> Permit Review											
Collins Academy High School	2008-1880-MCR-1	1703188	09-0422-PR10	3	GC Blidnerman Construction Company	CR2	(\$9,981)	\$217,040	\$3,036,000	\$3,243,359	6.83% 0
Description >> Credit unused allowances											
Reason >> Credit unused allowances. Project is complete.											
Justification >> Owner Directed											
Curie Metro High School	2010-53101-PLS	2007883	10-1922-PR8	4	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	1003	\$10,733	\$0	\$0	\$10,733	0.00% 0
Description >> Replace scheduled aluminum door frames with Stainless steel frames to comply with fire code. Provide transom info.											
Reason >> The specified aluminum frames could not attain the needed fire rating.											
Justification >> Code Change											

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Under \$50,000 and 10% (Cumulatively)**

**APPENDIX B
2/11/2011**

School	Project Num	Contract Num	Board Report REG	Type	GENERAL CONTRACTOR ARCHITECT OF REC.	COR # CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT % OF CON	TOT % OF TIME EXTN	
Curtis School	2010-23061-CSP	1956519	10-0728-PR10	6	GC Chicago Commercial Contractors, LLC	02 \$13,852	\$0	\$3,574,577	\$3,588,429	0.39%	0	
Description >> Provide pricing for the following work: In Lunchroom 011 of the Main Building, cut and remove the damaged portion of concrete floor slab and replace with new slab on grade per note 4 on S1.Ra. Cut control joints to match existing.												
Reason >> Upon removal of existing hardwood flooring, we discovered that the existing concrete substrate had heaved and needed to be removed and replaced in order to be reused as the floor for the new Cafeteria.												
Justification >> Discovered or Changed Conditions												
Description >> Install 30 coat hooks in each classroom in the Annex Building.												
Reason >> School request to replace old/existing coat hooks.												
Justification >> Owner Directed												
Dunbar High School	2010-53021-ADA	1893527	10-0428-PR8	4	GC Reliable & Associates Construction Co.	CPS4 \$4,680	\$104,592	\$2,407,078	\$2,516,350	4.54%	0	
Description >> Additional compensation for apprentice wages to satisfy wages agreement.												
Reason >> As agreed by CPS, Reliable, and Union Officials.												
Justification >> Owner Directed												
Dunbar High School	2010-53021-CAR-1	1935150	10-0623-PR6	4	GC Fiedler Construction Co.	1017	\$10,391	\$23,585	\$1,628,000	\$1,661,976	2.09%	0
Description >> Additional glaze brick at south side of school outside of Auto Labs.												
Reason >> Base already includes minor brick replacement at each side of the existing overhead doors. However the remaining brick cannot be salvaged and should be replaced to match the new brick being installed by the project.												
Justification >> Discovered or Changed Conditions												
Dunbar High School	2010-53021-CAR-1	1935150	10-0623-PR6	4	GC Fiedler Construction Co.	1028	\$2,350	\$23,585	\$1,628,000	\$1,653,935	1.59%	0
Description >> ALLOWANCE - Provide new faucets for sink in carpentry lab.												
Reason >> The faucets were supposed to be existing from a previous project, however they cannot be located and new faucets need to be provided.												
Justification >> Discovered or Changed Conditions												
Description >> ALLOWANCE - In room 122 relocate H&C waterlines. In courtyard outside of carpentry lab provide new water connection to for new hose bib. In room 115 provide new vent line for new sinks. As per RFI # 5 and 29R.												
Reason >> The drawings call for connections of new piping to water and vent lines in locations which do they do not exist.												
Justification >> Error/Omission (AOE)												
Dunbar High School	2010-53021-CAR-1	1935150	10-0623-PR6	4	GC Fiedler Construction Co.	30	\$2,968	\$23,585	\$1,628,000	\$1,654,553	1.63%	0
Description >> Additional 1300sf of sod at courtyard.												
Reason >> The base contract drawings called for sod to be installed in the courtyard but to leave the existing perimeter band of dirt undisturbed. Given the poor condition of this area, sod should be installed throughout the courtyard.												
Justification >> Discovered or Changed Conditions												
Dvorak Academy	2009-6760-MCR	1766527	09-0722-PR6	3	GC Reliable & Associates Construction Co.	1013	\$5,200	\$204,307	\$2,495,988	\$2,705,495	8.39%	0
Description >> Provide a new storm pipe at roof D												
Reason >> The roof plan showed 2 drains but the existing roof only had one drain. A second roof drain was added.												
Justification >> Error/Omission (AOE)												
Dvorak Academy	2009-6760-MCR	1766527	09-0722-PR6	3	GC Reliable & Associates Construction Co.	1030	\$5,800	\$204,307	\$2,495,988	\$2,706,095	8.42%	0
Description >> Remove and replace soil vent stacks (13)												
Reason >> The vent stacks are required to be changed to clear the new roof by 14".												
Justification >> Discovered or Changed Conditions												
Ebinger School	2010-3150-MCR	1819335	09-1028-PR3	1	GC Reliable & Associates Construction Co.	1007	\$40,000	\$276,017	\$3,357,162	\$3,673,179	9.41%	0
Description >> Per Owner's Request, resurface entire lot: pave along side of building, haul away spoils to CID Special Waste Dump Site												
Reason >> Owner's Request to provide new asphalt throughout lot and along side of building												
Justification >> Owner Directed												

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Under \$50,000 and 10% (Cumulatively)**

**APPENDIX B
2/11/2011**

School	Project Num	Contact Num	Board Report REG	Type	GENERAL CONTRACTOR ARCHITECT OF REC.	COR # CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	% OF TIME EXTN		
Farragut Academy	2010-53091-PLS	2007886	10-0922-PR8	4	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	(\$6,250)	\$72,741	\$1,113,000	\$1,179,491	5.97%	0		
Description >> Provide credit for floor drain work and drinking fountain work. Reason >> Due to obstructions in construction the work is no longer required. Justification >> Discovered or Changed Conditions	Farragut Academy	2010-53091-PLS	2007886	10-0922-PR8	4	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	\$4,000	\$72,741	\$1,113,000	\$1,189,741	6.89%	0	
Description >> Provide CMU wall in lieu of drywall partition Reason >> The drywall partition will not be a durable application. The CMU will provide a stronger solution. Justification >> Owner Directed	Gladstone School	2009-3540-ADA	1884785	10-0324-PR4	3	GC Chicago Commercial Contractors, LLC	01	\$18,880	\$26,508	\$1,185,773	\$1,231,161	3.83%	0
Description >> Install four additional visual devices and four additional pull stations and remove and relocate one pull station and one visual device in the Health Clinic. Reprogram FACP as necessary to accommodate the changes. Reason >> Scope should have been included in base scope. Justification >> Error/Omission (AOI)	Gregory School	2010-23441-ROF-JOC	2009462	10-0922-PR8	3	GC Miller	01	\$25,525	\$0	\$1,428,509	\$1,454,034	1.79%	0
Description >> Provide repair of existing trusses and lintel at the south side of the courtyard as shown on attached sketches SSK001, SSK002, SSK003 and SSK004. Provide rubberized asphalt flashing at the third floor lintel. Reason >> Upon removal of existing masonry for investigations, we discovered that the truss behind the lintel is rusted and pushing out the masonry. It is also causing the lintel to rotate. Need to repair truss, replace lintel and rebuild masonry. Justification >> Discovered or Changed Conditions	Gregory School	2010-23441-ROF-JOC	2009462	10-0922-PR8	3	GC Miller	02	\$27,066	\$0	\$1,428,509	\$1,455,575	1.89%	0
Description >> Provide demolition of existing courtyard skylight and roof infill as shown on attached sketches ASK-003, ASK-004, ASK-005, SSK-100b and SSK-30a. Reason >> The existing skylight is old and original to the building. Recommend demolishing/removing the existing skylight and roofing over the opening to prevent future maintenance issues. Justification >> Discovered or Changed Conditions	Gregory School	2010-23441-ROF-JOC	2009462	10-0922-PR8	3	GC Miller	03	\$18,086	\$0	\$1,428,509	\$1,446,594	1.27%	0
Description >> Provide revised roof sheathing and sleepers in section shown on attached RFI 17-R and provide 2x4 sleepers and 3/4" TG plywood sheathing to match adjacent construction as described in Keynote #8 on Sheet S1.4 and shown in Detail 6/S3.0. Contractor shall confirm that the lookouts were not disturbed and are still firmly attached. If they are loose, notify AOR immediately. Reason >> Upon removal of existing roofing, we discovered 700 SF of additional decking and sleepers that need to be removed and replaced. Justification >> Discovered or Changed Conditions	Gregory School	2010-23441-ROF-JOC	2009462	10-0922-PR8	3	GC Miller	04	\$28,154	\$0	\$1,428,509	\$1,456,662	1.97%	0
Description >> Provide revised roof sleeper attachments as shown on attached sketches. Reason >> Upon installing a test installation of the specified sleeper attachments, we discovered that the existing structural clay tie face shells are too brittle for proper support. Need to install adoptions/timbs to obtain proper support. Justification >> Discovered or Changed Conditions													

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Under \$50,000 and 10% (Cumulatively)**

APPENDIX B
2/11/2011

School	Project Num.	Contract Num.	Board Report REG	Type	GENERAL CONTRACTOR ARCHITECT OF REC. Inc.	COR# CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	% OF TIME EXTN	
Marshall High School (See Faraday 46-40)	2010-47041-MCR	1888105	10-0324-PR4	3	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	1028 (\$6,323)	\$70,287	\$6,030,000	\$6,093,964	1.06%	0	
Description >> Credit for deletion of replacement of 6 limestone coping pieces.												
Reason >> Following the start of construction it was determined that the limestone pieces were in good condition and did not require replacement.												
Justification >> Discovered or Changed Conditions												
Pulaski Academy	2010-31211-CSP	1962948	10-0728-PR10	2	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	03	\$30,500	\$24,920	\$1,791,000	\$1,846,420	3.09%	0
Description >> Provide labor and materials to completely finish clean both buildings for start of school. Costs should include 3 coats of wax on all VCT flooring in both buildings and finish clearing of all surfaces including bathrooms and classroom shelving.												
Reason >> School request to clean buildings before start of school.												
Justification >> Owner Directed												
Description >> Modify circulation desk to accommodate younger students. Infill openings, remove existing tackboards and built-in shelving and patch and paint walls to accommodate new library shelving.												
Reason >> Work required to allow Department of Libraries to install new shelving for new library.												
Justification >> Owner Directed												
Pulaski Academy	2010-31211-CSP	1962948	10-0728-PR10	2	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	04	\$4,109	\$24,920	\$1,791,000	\$1,820,029	1.62%	0
Description >> Provide labor and materials to troubleshoot and repair the existing fire alarm in the Annex Building.												
Reason >> School request to fix fire alarm that was down. FHP's electrician removed and replaced one device and one pull station in addition to troubleshooting and wiring replacement.												
Justification >> Errata/Omission (AOI)												
Pulaski Academy	2010-31211-CSP	1962948	10-0728-PR10	2	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	05	\$14,779	\$24,920	\$1,791,000	\$1,830,699	2.22%	0
Description >> Re-pipe existing unit vents to facilitate proper drainage out of the units.												
Reason >> Existing unit vents are piped improperly in a way that forces the condensate to drain back into the units (causing the leaks and finish damages we renovated in the project). In order to correct the leak, the internal piping needs to be removed, replaced, relocated, and repatched for proper drainage. Also, the existing condensate drain piping is not long enough to drain outside the building. Need to extend drain piping to allow proper drainage.												
Justification >> Discovered or Changed Conditions												
Description >> Provide 3 new occupancy sensors in the Main Building Lunch Room and Library.												
Reason >> Not enough occupancy sensors were specified for proper lighting controls of the spaces.												
Justification >> Errata/Omission (AOI)												
Pulaski Academy	2010-31211-CSP	1962948	10-0728-PR10	2	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	CSP02	\$34,569	\$24,920	\$1,791,000	\$1,850,489	3.32%	0
Description >> Main Building: Change all corridor doors altered in this project to new C Label doors in HJM frames with wood trim. Provide new wire glass transom. Annex Building: Change all corridors altered in this project to new C Label wood doors with 1/4" wire glass vision panel to match existing. New HJM metal frames to be C Label.												
Reason >> Comments made during permit review for rating.												
Justification >> Permit Review												
Satin Magnet	2007-7790-BLR	1723713	09-0624-PR8	2	GC Fiedler Construction Co.	1015	\$3,077	\$120,385	\$2,111,800	\$2,235,262	5.85%	0
Description >> Install phone and data line in the engineer's office												
Reason >> The contract drawings indicated that the building engineer's office was located near the boiler room. The engineers office is located under the south east stair.												
Justification >> Errata/Omission in Contract Documents												
Schurz High School	2008-1530-BLR	1909837	10-0326-PR3	1	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	31	\$34,878	\$21,203	\$10,445,000	\$10,508,081	0.80%	0
Description >> Add new exhaust fan EF-7B.												
Reason >> After the existing fans were tested and surveyed, they were found to be deficient.												
Justification >> Discovered or Changed Conditions												

CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS

March Change Order Log
Changes Under \$50,000 and 10% (Cumulatively)

School	Project Num	Contract Num	Board Report REG	TYPE	GENERAL CONTRACTOR ARCHITECT OF REC. Inc.	COR # CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	TOT % OF TIME EXTN	
Schurz High School	2006-1530-BLR	1903837	10-0526-PR3	1	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	\$7,133	\$28,203	\$10,445,000	\$10,480,336	0.34%	0	
Description >> Fire escape modifications to accommodate the new ductwork.												
Reason >> The original design was in conflict with field conditions and modifications to newly installed ductwork.												
Justification >> Error/Omission (AOE)												
Schurz High School	2006-1530-BLR	1903837	10-0526-PR3	1	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	\$6,103	\$28,203	\$10,445,000	\$10,479,306	0.33%	0	
Description >> Remove existing masonry infill at combustion air louvers.												
Reason >> The existing windows were in filled with masonry and needed to be removed to install louvers.												
Justification >> Error/Omission (AOE)												
Schurz High School	2006-1530-BLR	1903837	10-0526-PR3	1	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	\$6,000	\$28,203	\$10,445,000	\$10,479,203	0.33%	0	
Description >> Additional steel and maintenance platform at RF-3A and RF-3B.												
Reason >> Platforms required for servicing the return fans.												
Justification >> Error/Omission (AOE)												
Schurz High School	2010-46281-ADA	1903854	10-0428-PR8	1	GC Chicago Commercial Contractors, LLC	26A	\$9,777	\$276,113	\$3,584,258	\$3,870,148	7.98%	0
Description >> Abatement for wood flooring with acm under flooring.												
Reason >> ACM was discovered under the vct flooring.												
Justification >> Discovered or Changed Conditions												
Schurz High School	2010-46281-ADA	1903854	10-0428-PR8	1	GC Chicago Commercial Contractors, LLC	72	\$4,887	\$276,113	\$3,584,258	\$3,965,258	7.94%	0
Description >> Provide new gypsum board chase wall and electric for sink in Dark Room 112.												
Reason >> Chase wall needed to be installed to facilitate the plumbing.												
Justification >> Error/Omission (AOE)												
Schurz High School	2010-46281-ADA	1903854	10-0428-PR8	1	GC Chicago Commercial Contractors, LLC	92	\$4,810	\$276,113	\$3,584,258	\$3,865,181	7.94%	0
Description >> Provide hot water to convenience sink in cafeteria from floor below.												
Reason >> No hot water was running to the sink.												
Justification >> Discovered or Changed Conditions												
Schurz High School	2010-46281-ADA	1903854	10-0428-PR8	1	GC Chicago Commercial Contractors, LLC	7t	\$10,986	\$276,113	\$3,584,258	\$3,871,357	8.01%	0
Description >> Repair and adjust various existing doors to fit properly in existing openings.												
Reason >> Various existing doors needed repair after proper fit throughout the school.												
Justification >> Owner Directed												
Senn High School, Nicholas	2007-1540-BLR	1913075	10-0526-PR3	1	GC Miner	23	\$5,128	\$29,223	\$9,540,000	\$9,574,351	0.36%	0
Description >> Pool RTU-1 condensate drain heat tracing.												
Reason >> This change is for freeze protection.												
Justification >> Error/Omission (AOE)												
Senn High School, Nicholas	2007-1540-BLR	1913075	10-0526-PR3	1	GC Miner	25	\$8,000	\$29,223	\$9,540,000	\$9,577,223	0.39%	0
Description >> Remove existing access door to catwalk. Provide 2 hour rated wall system. Provide 2 hour rated access panel 24" x 48". Contractor to patch and paint. Infill existing concrete base at bottom of metal panel with lign weight concrete.												
Reason >> This work is required to obtain a 2 hour fire separation in the boiler room.												
Justification >> Error/Omission (AOE)												

11-0323-PR6

APPENDIX B

2/11/2011

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Over \$50,000 or 10% (Cumulatively)**

11-0323-PR6

APPENDIX C

2/17/2011

School	Project Num	Contract Num	Board Report REG	TYPE	GENERAL CONTRACTOR ARCHITECT OF REC.	COR # CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	TOT % OF TIME EXTN
Amundsen High School	2010-46031-ADA	1853516	10-0428-PR8	1	GC Miller	54	\$18,818	\$607,836	\$2,539,000	\$3,165,654	24.68% 0
Description >> Remove stainless steel panels and infill with glazed cmu in (8) openings in the Pool Area. Reason >> The school has requested that the stainless steel be replaced with glazed cmu for less maintenance and aesthetics reasons. Justification >> Owner Directed											
Cardenais School	2010-24051-RCF	1918403	10-0526-PR3	4	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	CR1	(\$14,955)	\$83,959	\$328,000	\$396,964	21.03% 0
Description >> Credit remaining allowances Reason >> Credit remaining allowance because project has been completed. Justification >> Owner Directed											
Clemente Academy	2010-51091-PLS	2003748	10-0825-PR3	2	GC All-Bry Construction	002	(\$2,000)	\$82,000	\$627,000	\$707,000	12.76% 0
Description >> CREDIT: Existing drywall boards (2 each) to remain Reason >> DM requested that all drywall boards remain in place - no work. Justification >> Owner Directed											
Clemente Academy	2010-51091-PLS	2003748	10-0825-PR3	2	GC All-Bry Construction	007	\$85,780	\$82,000	\$627,000	\$794,780	26.76% 0
Description >> Replace 47 - 2x2 ceiling mounted natalodium light fixtures per architectural specification Reason >> Existing ceiling mounted pool lights are in disrepair. Many need new ballasts & wiring; many have missing reflectors; wire insulation is brittle and crumbling; lens gaskets are dry-rotted. Justification >> Owner Directed											
Ebinger School	2010-3150-MCR	1819335	09-1028-PR3	1	GC Reliable & Associates Construction Co.	1005	\$159,363	\$276,017	\$3,357,162	\$3,792,542	12.97% 0
Description >> Provide repairs for demolition and parapet rebuild at the north and south elevations, approx. 220LF; Provide credit for installation of helical anchors removed from scope at the north elevation; approx. 1700SF Reason >> North and south parapet walls are in deteriorated condition - too weak to hold helical anchors without failing apart - cannot just be tuckpointed. Justification >> Error/Omission (DM)											
Farnen School	2009-33000-ADA	1817020	09-1028-PR3	4	GC Chicago Commercial Contractors, LLC	CR1	(\$774)	\$125,550	\$960,012	\$1,084,788	13.00% 0
Description >> Credit unused allowances. Reason >> The job is complete. Justification >> Owner Directed											
Gage Park High School	2010-46141-PLS	2007890	10-0922-PR8	5	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	1	\$20,665	\$166,371	\$697,000	\$884,036	26.83% 0
Description >> Provide (4) new trees in pathway (no grates); Demo existing door at Boys Locker 110; Provide door G110C; Provide (3) Type S7 signs and (5) Type S8 signs; Provide (4) additional exit signs within Boys Locker 110; Reason >> Building Dept. and IDPH revisions. Justification >> Permit Review											
Gage Park High School	2010-46141-PLS	2007890	10-0922-PR8	5	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	117	\$1,861	\$166,371	\$697,000	\$865,032	24.11% 0
Description >> Provide ceramic tile at the walls of the shower stall only within Unisex changing 102c Reason >> Add tile in 102C due to delamination of shower liner system as specified Justification >> Error/Omission (AOR)											

**CHICAGO PUBLIC SCHOOLS
DEPARTMENT OF OPERATIONS**

**March Change Order Log
Changes Over \$50,000 or 10% (Cumulatively)**

APPENDIX C

2/17/2011

School	Project Num	Contract Num	Board Report REG	Type	GENERAL CONTRACTOR ARCHITECT OF REC.	COR # CO AMOUNT	PREVIOUS APPROVED CHANGES	ORIGINAL CONTRACT AMOUNT	REVISED CONTRACT AMOUNT	TOT CON	% OF TIME EXTN		
Mason School	2008-4650-ADA	175469	09-0722-PR8	3	GC F.H. Paschen, S.N. Nielsen & Assoc., Inc.	\$634	\$507.779	\$1,592,000	\$2,100,413	31.94%	0		
					Description >> Lower plumbing trap at ada sink in science lab. Reason >> The case work would not fit with the existing piping and the piping impeded the required ada knee space. Justification >> Discovered or Changed Conditions								
Mather High School	2007-1480-CSP	1726765	09-0624-PR8	1	GC Tyler Lane Construction, Inc.	BUL.80F	\$215,326	\$1,431,747	\$27,189,127	\$28,836,199	6.06%	0	
					Description >> Convert teacher workroom 218 to Chemistry Lab to satisfy ID's requirements. Includes Millwork, plumbing, teacher demonstration table, fume hood, student desks, sinks and adjacent prep room. THIS SHALL INCLUDE ALL PREMIUM TIME AS NECESSARY TO COMPLETE THE WORK BY 1/2/2011. Reason >> Current enrollment cannot be supported in existing science labs; Lab is required by ID's to assist Mather students in achieving Adequate Yearly Progress (AYP). Justification >> Owner Directed								
Mollison School	2008-6950-BLR	1678809	09-0225-PR4	4	GC Chicago Commercial Contractors, LLC	STDB7	\$11,825	\$45,933	\$2,156,998	\$2,624,756	21.69%	0	
					Description >> Additional Cx issues Reason >> The change to the base scope was made by the Cx agent. Justification >> Owner Directed								
Mollison School	2009-6950-ADA	183084	09-1123-PR6	4	GC Chicago Commercial Contractors, LLC	1019	\$6,238	\$128,434	\$663,099	\$997,771	15.60%	0	
					Description >> Provide power for faucets at sink in 4 restrooms Reason >> The sinks were changed out per the bathroom beautification scope and the power for the faucets was not specified. Justification >> Owner Directed								
Morgan Park High School	2010-46251-PLS	2007914	10-0922-PR8	6	GC Miller		10	\$4,427	\$84,539	\$560,000	\$648,966	15.89%	0
					Description >> IDPH changes - float valve Reason >> Per IDPH comments provide new 3" float valve, extension of fill pipe, and butterfly gear valve Justification >> Permit Review								
Morgan Park High School	2010-46251-PLS	2007914	10-0922-PR8	6	GC Miller		12	\$15,828	\$84,539	\$560,000	\$660,367	17.92%	0
					Description >> Replacement light fixtures due to incorrectly specified fixture type for grid ceiling Reason >> Incorrect light fixture type was specified Justification >> Error/Omission (AOR)								
Morgan Park High School	2010-46251-PLS	2007914	10-0922-PR8	6	GC Miller		13	(\$881)	\$84,539	\$560,000	\$643,659	14.94%	0
					Description >> Provide credit for heat coil not provided. Actuator work to be completed without controls Reason >> Heating coil was cleaned and inspected and discovered it can not be repaired Justification >> Discovered or Changed Conditions								
Morgan Park High School	2010-46251-PLS	2007914	10-0922-PR8	6	GC Miller		24	\$9,812	\$84,539	\$560,000	\$654,351	16.85%	0
					Description >> Electrical code compliance revisions . Reason >> Electrical code compliance changes per IDPH. Justification >> Code Change								
Morgan Park High School	2010-46251-PLS	2007914	10-0922-PR8	6	GC Miller		9	\$4,571	\$84,539	\$560,000	\$649,110	15.91%	0
					Description >> Add six (6) cut type rope line anchors to pool wall above existing rope line anchors that are damaged. Reason >> Per school request, as existing anchors are in need of replacement. Justification >> Owner Directed								

