

**APPROVE THE AWARD OF CONSTRUCTION CONTRACTS AND APPROVE CHANGES TO  
CONSTRUCTION CONTRACTS FOR THE BOARD OF EDUCATION'S CAPITAL IMPROVEMENT  
PROGRAM**

**THE CHIEF EXECUTIVE OFFICER REPORTS THE FOLLOWING DECISION:**

Approve the award of Capital Improvement Program construction contracts in the total amount of \$96,362,612.58 to the respective lowest responsible bidders for various construction projects, as listed in Appendix A of this report. These construction contracts shall be for projects approved as part of the Board's Capital Improvement Program. Work involves all labor, material and equipment required to construct new schools, additions, and annexes, or to renovate existing facilities, all as called for in the plans and specifications for the respective projects. Proposals, schedules of bids, and other supporting documents are on file in the Department of Operations. These contracts have been awarded in accordance with section 7-3 of the Rules of the Board of Education of the City of Chicago.

Approve changes to existing Capital Improvement Program construction contracts, in the amount of \$171,089 as listed in Appendix B of this report. These construction contract changes have been processed and are being submitted to the Board for approval in accordance with section 7-15 of the Rules of the Board of Education of the City of Chicago.

Approve changes to existing Capital Improvement Program construction contracts, in the amount of \$503,766 listed in Appendix C of this report. These construction contract changes are being submitted to the Board for approval prior to processing in accordance with section 7-15 of the Rules of the Board of Education of the City of Chicago, since they require an increased commitment in excess of \$50,000 or 10% of the original contract amount, whichever is less, or, as provided under Section 7-5 of the Rules, are necessitated by an unforeseen combination of circumstances or conditions calling for immediate action to protect Board property or to prevent interference with school sessions.

**LSC REVIEW:** Local School Council approval is not applicable to this report.

**AFFIRMATIVE ACTION:** The General Contracting Services Agreements entered into by each of the pre-qualified general contractors and other miscellaneous construction contracts awarded outside the pre-qualified general contractor program for new construction awards and changes to existing construction contracts shall be subject to the Board's Business Diversity Program for Construction Projects and any revisions or amendments to that policy that may be adopted during the term of any such contract.

**FINANCIAL:** Expenditures involved in the Capital Improvement Program are charged to the Department of Operations, Capital Improvement Program.

Budget classification: Fund – 436, 468, 476, 477, 479, 480, 481, 482 will be used for all Change Orders (Appendix B & C); Funding source for new contracts is so indicated on Appendix A

Funding Source: Capital Funding

**GENERAL CONDITIONS:**

Inspector General – Each party to the agreement shall acknowledge that, in accordance with 105 ILCS 5/34-13.1, the Inspector General of the Chicago Board of Education has the authority to conduct certain investigations and that the Inspector General shall have access to all information and personnel necessary to conduct those investigations.


Conflicts – The agreement shall not be legally binding on the Board if entered into in violation of the provisions of 105 ILCS 5/34-21.3 which restricts the employment of, or the letting of contracts to, former Board members during the one year period following expiration or other termination of their terms of office.

Indebtedness – The Board's Indebtedness Policy adopted June 26, 1996 (96-0626-PO3), as amended from time to time, shall be incorporated into and made a part of the agreement.

Ethics – The Board's Ethics Code adopted June 23, 2004 (04-0623-PO4), as amended from time to time, shall be incorporated into and made a part of the agreement.

Contingent Liability – The agreement shall contain the clause that any expenditure beyond the current fiscal year is deemed a contingent liability, subject to appropriation in the subsequent fiscal year budget(s).


**Approved for Consideration:**

  
\_\_\_\_\_  
Opal L. Walls  
Chief Purchasing Officer

**Approved:**

  
\_\_\_\_\_  
Terry Mazany  
Chief Executive Officer

**Within Appropriation:**

  
\_\_\_\_\_  
Diana S. Ferguson  
Chief Financial Officer

**Approved as to legal form:**

  
\_\_\_\_\_  
Patrick J. Rocks  
General Counsel

**Appendix A**  
**May 2011**

| REG. | SCHOOL                   | CONTRACTOR   | WORK DESCRIPTION | CONTRACT AWARD DATE | AWARD DATE | PROJECT COMPLETE | FISCAL YEAR   | CIP BUDGET    | FUND CONTRACT # | PROJECT SCOPE AND NOTES |   | ANTICIPATED COMPLETE |
|------|--------------------------|--|------------------|---------------------|------------|------------------|---------------|---------------|-----------------|-------------------------|---|----------------------|
|      |                          |  |                  |                     |            |                  |               |               |                 |                         |   |                      |
| 1    | Disney II Magnet         | F.H. Paschen, S.N. Nielsen & Assoc., Inc.                  | BLR-Renovation   | \$ 3,286,000.00     | 3/19/2011  | 2011             | \$ 4,827,718  | \$ 4,460,000  | 482             | 2112169                 | 15% ADA Upgrade: Roof replacement, roof drains, masonry, Boiler Up-grade, dehumidification.   | 12/30/2011           |
| 1    | Ebbing School            | K.R. Miller Contractors, Inc.                              | JOC              | \$ 98,872,00        | 3/29/2011  | 2010             | \$ 126,556    | \$ 108,979    | 477             | 2112431                 | The Scope of Work includes: Demolition and removal of existing doors. Installation of new doors. Masonry. Repair gypsum plaster wall. Prime and paint new doors   | 6/30/2011            |
| 1    | Farnsworth School        | All-Bry Construction                                       | MCR-Renovation   | \$ 2,499,000.00     | 3/29/2011  | 2011             | \$ 3,027,593  | \$ 3,800,000  | 482             | 2112412                 | A. The main focus of this project is to provide roof and exterior masonry renovations, select exterior and interior door replacement, address water-damaged interior finishes, toilet room renovations, lockers replacement, domestic HW and CW piping replacement, lighting replacement (except gymnasium and main corridors), and provide site scope for Landscape and Zoning ordinance compliance.   | 9/1/2011             |
| 1    | Hamilton School          | Reliable & Associates Construction Co.                     | FAS-Renovation   | \$ 214,768,00       | 4/15/2011  | 2011             | \$ 364,419    | \$ 375,000    | 482             | 2120780                 | Add Combination audio/visual fire alarm devices to existing system; Add Visual strobe fire alarm devices to existing system; Provide Wire Guards at existing audio/visual devices at Gym; Provide new emergency battery units; Replace existing battery exit signs for entire facility. Provide trash enclosure, accessible parking spaces, cedar fence.  | 9/30/2011            |
| 1    | Lane Tech High School    | Paul Borg Construction                                     | JOC              | \$ 15,947,40        | 4/20/2011  | 2010             | \$ -          | \$ 15,947     | 477             | 2122082                 | The intent of this project is to install a pool cover.  | 11/30/2011           |
| 1    | Mather High School       | Paul Borg Construction                                     | JOC              | \$ 13,550,31        | 4/21/2011  | 2007             | \$ -          | \$ 13,550     | 476             | 2122595                 | The intent of this project is to install a pool cover.  | 11/30/2011           |
| 1    | Clemente Academy         | Paul Borg Construction Chicago Commercial Contractors, LLC | ADA-Renovation   | \$ 11,707,311.00    | 3/15/2011  | 2011             | \$ 14,011,128 | \$ 14,100,000 | 482             | 2105523                 | ADA Scope at Academic Building - Modernization of 2 existing elevators and of 12 existing escalators. Modifications to all student toilet rooms for ADA compliance Basement level to 8th floor. New unisex toilet rooms. New ADA ramps compliant band room. Modifications to the Auditorium for ADA compliance. New fire alarm and all MEP related scope, and exterior ramp at Plaza.   | 11/30/2011           |
| 2    | Clemente Academy         | F.H. Paschen, S.N. Nielsen & Assoc., Inc.                  | BLR-Renovation   | \$ 327,059.00       | 4/19/2011  | 2011             | \$ 501,819    | \$ 401,734    | 482             | 2121858                 | PENTHOUSE - Provide continuous metal angle to existing CMU to provide structural support. Remove and reinstall mechanical and electrical items as required. Remove existing louvers and reinstall at areas of masonry work.   | 4/19/2011            |
| 2    | Hanson Park School       | F.H. Paschen, S.N. Nielsen & Assoc., Inc.                  | BLR-Renovation   | \$ 6,426,000.00     | 4/7/2011   | 2011             | \$ 7,559,413  | \$ 7,690,000  | 482             | 2117060                 | Vault Building - Rebuild masonry enclosure section and provide new roof lights and parapets.  | 3/25/2011            |
| 2    | Lincoln Park High School | Paul Borg Construction                                     | JOC              | \$ 12,003,10        | 4/20/2011  | 2010             | \$ -          | \$ 12,003     | 477             | 2122166                 | Renovate the existing heat pump cooling/heating system by installing new heat pumps and a new cooling tower throughout the existing main building and additions. Provide an additional condensing boiler in the main building boiler room to supplement the heating capacity of the existing heating system. Provide new packaged DX cooled/hydronic heat unit ventilators throughout the Annex building. Provide a new web based ODC Building Automation System (BAS) for the complete HVAC system throughout the school including the Annex building. Provide new roof air main building and link to annex. Exterior masonry restoration. Renovate existing skylight. Stairs renovation on North side of building. 15% ADA upgrade.   | 4/25/2011            |
| 2    | Lincoln Park High School | Binderman Construction Company                             | ADA-Renovation   | \$ 7,924,000.00     | 3/11/2011  | 2011             | \$ 9,206,581  | \$ 9,300,000  | 482             | 2101598                 | The intent of this project is to install a pool cover.  | 11/30/2011           |
| 2    | Lincoln Park High School |  |                  |                     |            |                  |               |               |                 |                         | Lincoln Park High School ADA Improvements. Seal and stripe parking lot. Remove the locked ornamental metal gate. In the Main Building provide two new elevators: a 5-stop and a 4-stop hoists a 3000 lb hydraulic. Provide a 2-stop LULA elevator in the Annex Building. In both the Main and Annex Buildings. Provide new accessible corridor doors, remodel student restrooms, provide new unisex restrooms, provide new bleachers in gym including accessible bleacher seating, provide accessible Art rooms, Science Classrooms and Computer Classrooms, provide accessible corridor lockers, provide an accessible reception desk at main office, provide accessible drinking fountains, provide a new fire alarm system including audio/visual alarm devices, provide accessible signage, provide accessible courtyards. At the Main Building remodel the Library (remodel the Auditorium to make it accessible add a platform lift at the stage). At the Annex Building provide an accessible main entrance including power door operators and A1 phone (remodel the Men's and Women's locker rooms provide a Unisex Changing Room). | 3/25/2011            |

## Appendix A

| REG. SCHOOL   | CONTRACTOR                                | WORK DESCRIPTION | CONTRACT AWARD  | AWARD DATE | FISCAL YEAR | PROJECT COMPLETE | CIP BUDGET FUND CONTRACT# PROJECT SCOPE AND NOTES   |      | ANTICIPATED COMPLETE |
|---|---|------------------|-----------------|------------|-------------|------------------|---|------|----------------------|
|   |   |                  |                 |            |             |                  | CIP   | FUND |                      |
| 2 Payton High School  | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | MCR-Renovation   | \$ 5,025,000.00 | 3/29/2011  | 2011        | \$ 5,840,318     | \$ 6,000,000  | 482  | 2112413              |
| 2 Pritzker School   | K.R. Miller Contractors, Inc.             | BLR-Renovation   | \$ 2,991,000.00 | 3/29/2011  | 2011        | \$ 3,498,356     | \$ 4,400,000  | 482  | 2112418              |
| 2 Schubert School   | Tyler Lane Construction, Inc.             | MCR-Renovation   | \$ 4,791,894.00 | 3/25/2011  | 2011        | \$ 5,767,267     | \$ 6,330,000  | 482  | 2110460              |
| 2 Wells Academy High School   | K.R. Miller Contractors, Inc.             | PLS-Renovation   | \$ 2,331,600.00 | 4/6/2011   | 2011        | \$ 2,815,362     | \$ 2,990,000  | 482  | 2116196              |
| 3 Cooper School   | Wright & Company                          | FAS-Renovation   | \$ 498,156.00   | 4/25/2011  | 2011        | \$ 649,836       | \$ 550,000  | 482  | 2123391              |
| 3 Crane Tech High School  | CMM Group Inc                             | CAR-Renovation   | \$ 413,000.00   | 3/11/2011  | 2011        | \$ 528,942       | \$ 545,000  | 482  | 2101591              |
| 3 Dvorak Academy  | All-Bry Construction                      | BLR-Renovation   | \$ 3,419,000.00 | 3/29/2011  | 2011        | \$ 4,041,369     | \$ 4,300,000  | 482  | 2112411              |
| 3 Jefferson T School  | Wright & Company                          | JOC              | \$ 815,795.36   | 4/5/2011   | 2011        | \$ 962,488       | \$ 888,823  | 482  | 2116190              |
| 3 Juarez High School  | OCA Construction, Inc.                    | CAR-Renovation   | \$ 761,102.80   | 3/29/2011  | 2011        | \$ 938,580       | \$ 1,035,000  | 482  | 2112430              |
| 4 Curve Metro High School   | Paul Borg Construction                    | JOC              | \$ 16,637.85    | 4/20/2011  | 2010        | \$ -             | \$ 16,638   | 477  | 2122083              |
| 4 Curve Metro High School   | K.R. Miller Contractors Inc               | MFP-Renovation   | \$ 479,000.00   | 4/6/2011   | 2011        | \$ 565,195       | \$ 575,495  | 482  | 2110465              |
| 4 An interior and exterior renovation, the project completes the envelope project of 2010. A new roof with misc. masonry, window and curtain wall work to fix water infiltration issues that have plagued the building from its start. Interior work includes replacing water damaged materials as well as replacing data / power floor boxes in the academic wing, new fire code storage areas for the building and connecting punchlist items from the building opening.  |   |                  |                 |            |             |                  | The intent of this project is to install a pool cover.  |      |                      |
| 4 Renovate the existing heating only system and provide full air conditioning by installing new centralized air cooled chiller with dual temperature piping. Provide new dual temperature unit ventilators for the classrooms along with new dual temperature air handling units for the gym, auditorium and the cafeteria/kitchen. The existing newer hot water heating boilers are retained, however the remaining hydronic auxiliaries are replaced with new. Provide a new BAS in accordance with the CPS BAS Standards.  |   |                  |                 |            |             |                  | Remove existing rooftop unit serving the pool and install one pool dehumidification unit in its place. This scope also includes but not limited to ductwork modification, DDC control, structural support and electrical power connections.   |      |                      |
| 4 Masonry renovation with 15% ADA ERC Elevator Upgrades. Building envelope elements related to the roof, parapets and related systems, water damaged enclosure, windows and consequential damage to interior finishes constitute the basic scope of this proposed project. PPRZ (Zoning) and ADA site requirements are also included in the basic scope.  |   |                  |                 |            |             |                  | The pool will be outfitted with a new PVC liner and stainless steel gutter system. The pool filtration and pump system will be replaced. Dehumidification will be added to the natatorium. Concrete columns supporting pool will be reconstructed. The girls shower area to be reconstructed with all new plumbing. Excess program area in the girls locker room will be converted to a girls weight training room. The boys and girls locker rooms will be outfitted with accessible toilet, shower and locker facilities. The boys locker room floor will be outfitted with accessible toilet, shower and locker upgraded with updated valving and shower heads." |      |                      |
| <b>\$ 41,552,504.95</b>   |   |                  |                 |            |             |                  |   |      |                      |
| 4 Annex Building Only. Provide a new fire alarm system and devices per CPS standards. Provide new System 1 emergency system with natural gas generator. Provide new exit signs with integral battery, trash enclosures, generator enclosure, accessible parking spaces, ornamental fence, cedar fence, and tree and tree grate.   |   |                  |                 |            |             |                  | 9/30/2011   |      |                      |
| 4 2 New Career Academy Rooms (IT) & Minor ADA Enhancement at 4th Floor (Unisex Toilet) Renovation of the existing heating system and the cooling system. New boilers and new central air cooled chiller with dual temperature piping is provided throughout the school. In addition to comply with the fire department requirement and the City of Chicago Building Code, existing ceilings are removed throughout the school and replaced with one hour rated ceilings. Parallel to this work, new lighting fixtures are also provided wherever the ceilings are removed. Provide a new BAS in accordance with the CPS BAS Standards. (15% ADA Upgrade Tracking) |   |                  |                 |            |             |                  | 9/1/2011  |      |                      |
| 4 The intent of the project is to complete the environmental rough demolition and preliminary finishes ahead of the implementation of the upcoming capital project.   |   |                  |                 |            |             |                  | 5/13/2011   |      |                      |
| 4 Medical Classrooms, Drafting IT and Gaming Computer Labs, Cafeteria & Hospitality and required ADA items Fountain Replacement Renovation of existing Toilet rooms and Unisex toilet at Second Floor.  |   |                  |                 |            |             |                  | 9/1/2011  |      |                      |

**Appendix A**  
**May 2011**

## Appendix A

| REG. | SCHOOL                  | CONTRACTOR                                | WORK DESCRIPTION | CONTRACT AWARD  | PROJECT DATE | FISCAL YEAR | CIP BUDGET       | FUND CONTRACT# | PROJECT SCOPE AND NOTES |          | ANTICIPATED COMPLETE   |            |
|------|-------------------------|---|------------------|-----------------|--------------|-------------|------------------|----------------|-------------------------|----------|--|------------|
|      |                         |   |                  |                 |              |             |                  |                | COMPLETE                | NOTES    |  |            |
| 5    | O'Toole School          | Blunderman Construction Company           | SIP-Renovation   | \$ 7,594,500.00 | 3/29/2011    | 2011        | \$ 8,980,115     | \$ 9,320,000   | 482                     | 2112415  | MCR, 15% ADA Full, BLR: This project is a School Improvement Program. The following elements will be provided: New ornamental iron fence at the parking lot, ADA parking spaces and exterior directional signage, new chain-link trash enclosure, new parkway trees, new roof hatch and ladders, rod and repair roof drain assemblies; replacement of select areas of the roof system down to deck, replace select exhaust fans, new exterior roof mounted light fixtures, tuck-point facades, rebuild parapets, new scuppers, cap chimney, new limits where required, new windows, patch terra cotta and tile, replace lot entrances, replace exterior doors, new elevator, replace selected classroom tile ceiling systems, patch and repair areas of damage cause by envelope leak issues, replace a single drinking fountain for accessibility, renovate one girls and one boys student toilet room, provide new revised curb cuts. Parking lot improvements include new site drainage, fencing and landscaping. Replace asphalt paving at existing northeast playlot area. Replace existing trash enclosure. Remove existing asphalt at parkways, provide new landscape materials and new trees as required by CBC Landscape Ordinance. Provide new emergency diesel generator and enclosure. Provide 3 new exterior ramps at accessible entrances. Replace exterior doors. Rebuild existing roof parapets at 1915 building. Tuckpoint portions of existing masonry, chimney and terra cotta and limestone trim. Replace existing roof system at 1915 and 1973 buildings. Replace existing damaged window spandrel panels at 1973 building. Provide one new elevator serving all levels of both buildings. Provide new accessible classroom doors; remodel student toilet rooms; provide new unisex toilet rooms; provide accessible drinking fountains; provide a new fire alarm system, including audio/visual devices; provide accessible signage; remodel existing assembly hall to provide accessibility including stage lift. | 12/31/2011 |
| 5    | Sexton School           | Friedler Construction Co.                 | ADA-Renovation   | \$ 5,775,800.00 | 3/30/2011    | 2011        | \$ 7,068,229     | \$ 7,140,000   | 482                     | 2113003  | Remove existing asphalt parking lot and replace with new, including new and revised curb cuts. Parking lot improvements include new site drainage, fencing and landscaping. Replace asphalt paving at existing northeast playlot area. Replace existing trash enclosure. Remove existing asphalt at parkways, provide new landscape materials and new trees as required by CBC Landscape Ordinance. Provide new emergency diesel generator and enclosure. Provide 3 new exterior ramps at accessible entrances. Replace exterior doors. Rebuild existing roof parapets at 1915 building. Tuckpoint portions of existing masonry, chimney and terra cotta and limestone trim. Replace existing roof system at 1915 and 1973 buildings. Replace existing damaged window spandrel panels at 1973 building. Provide one new elevator serving all levels of both buildings. Provide new accessible classroom doors; remodel student toilet rooms; provide new unisex toilet rooms; provide accessible drinking fountains; provide a new fire alarm system, including audio/visual devices; provide accessible signage; remodel existing assembly hall to provide accessibility including stage lift.  | 11/15/2011 |
| 5    | Simeon High School      | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | MEP-Renovation   | \$ 555,000.00   | 4/6/2011     | 2011        | \$ 665,155       | \$ 679,835     | 482                     | 2116202  | Remove existing air handling unit serving the pool and install one pool dehumidification unit in its place. This scope also includes but not limited to ductwork modification, remote condenser, controls, structural and electrical modifications.  | 8/19/2011  |
|      |                         |   |                  |                 |              |             | \$ 28,152,557.74 |                |                         |          |  |            |
| 6    | Carver Military Academy | Paul Bang Construction                    | JOC              | \$ 16,637,85    | 4/20/2011    | 2010        | \$ -             | \$ 16,638      | 477                     | 21122164 | The intent of this project is to install a pool cover.   | 11/30/2011 |
| 6    | Curtis School           | Chicago Commercial Contractors, LLC       | MCR-Renovation   | \$ 3,250,000.00 | 4/12/2011    | 2011        | \$ 3,855,455     | \$ 5,640,000   | 482                     | 2113001  | The primary scope of work for this project entails work on the roof and the building envelope. Work on the roof for this project includes removing and replacing the existing built-up roof system, rebuilding existing parapets, removing and reinstalling various rooftop mechanical units, removing and replacing with new roof mounted area lighting and new roof curb extensions and counter flashings. Work on the building envelope for this project includes replacing damaged windows and door lintels, restoring deteriorated brick walls, and providing site scope for Landscape and Zoning ordinance compliance. 15% ADA Upgrade.  | 8/31/2011  |
| 6    | Haley, Alex School      | Chicago Commercial Contractors, LLC       | MCR-Renovation   | \$ 2,363,718.00 | 3/30/2011    | 2011        | \$ 2,769,652     | \$ 5,720,000   | 482                     | 2112420  | 15% ADA Full, Exterior envelope renovation.  | 12/31/2011 |
| 6    | Morgan Park High School | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | MEP-Renovation   | \$ 617,000.00   | 4/6/2011     | 2011        | \$ 735,982       | \$ 743,930     | 482                     | 2116198  | Disconnect the air supply to the pool area from the existing air handling unit. Replace the steam coils on the existing AHU. Install one pool dehumidification unit on the roof. This scope includes but not limited to ductwork modification, architectural modifications and electrical power connections to the pool unit. Extended gas piping to roof. Provide acoustical treatment around the rooftop unit.   | 8/19/2011  |
| 6    | Sutherland School       | CMM Group Inc                             | SIP-Renovation   | \$ 5,102,200.00 | 4/15/2011    | 2011        | \$ 6,548,416     | \$ 7,300,000   | 482                     | 2120792  | Site scope to comply with Landscape and Zoning Ordinance compliance including new ornamental steel picket fencing along parking lot, new trash enclosure, new ADA parking stall signage and wheelchair stops, roof hatch and ladder replacements (with roof repairs under separate funding by Operations), exterior and interior masonry and structural renovations, select exterior door replacement, interior water-damaged finishes complete toilet room renovations for ADA compliance including all fixtures and fixtures, Boiler replacement, re-commissioning of UPS system, chilled water, hot domestic hot and cold water piping replacement and ADA scope to satisfy 15% ADA requirements. 15% ADA Upgrades.   | 9/1/2011   |

**Appendix A**

| REG. SCHOOL              | CONTRACTOR             | WORK DESCRIPTION | CONTRACT AWARD   | AWARD DATE | FISCAL YEAR | PROJECT COMPLETE | CIP BUDGET       | FUND CONTRACT # | PROJECT SCOPE AND NOTES | May 2011   |        | ANTICIPATED COMPLETE |            |
|--------------------------|------------------------|------------------|------------------|------------|-------------|------------------|------------------|-----------------|-------------------------|--|--------|----------------------|------------|
|                          |                        |                  |                  |            |             |                  |                  |                 |                         | \$   | 16,795 | 477                  |            |
| 6 Washington High School | Paul Borg Construction | JOC              | \$ 16,795.22     | 4/25/2011  | 2010        | \$ -             | \$ 16,795        | 477             | 2123371                 | The intent of this project is to install a pool cover. |        |                      | 11/30/2011 |
|                          | All Work Total:        |                  | \$ 11,366,351.07 |            |             |                  | \$ 96,362,612.58 |                 |                         |  |        |                      |            |

| REG. | SCHOOL   | Affirmative Action |    |    |    | WBE |
|------|--|--------------------|----|----|----|-----|
|      |  | AA                 | H  | A  | D  |     |
| 1    | Disney II Magnet                                 | T                  | B  | D  | 5  | 5   |
| 1    | Ebinger School                                   | 0                  | 38 | 0  | 5  | 5   |
| 1    | Farnsworth School                                | 0                  | 36 | 0  | 5  | 5   |
| 1    | Hamilton School                                  | T                  | B  | D  | 0  | 0   |
| 1    | Lane Tech High School                            | 0                  | 0  | 76 | 0  | 0   |
| 1    | Mather High School                               | 0                  | 0  | 72 | 0  | 0   |
| 2    | Clemente Academy                                 | 0                  | 0  | 76 | 0  | 0   |
| 2    | Clemente Academy                                 | 13                 | 13 | 4  | 5  | 5   |
| 2    | Clemente Academy                                 | 26                 | 2  | 0  | 13 | 13  |
| 2    | Hanson Park School                               | 28                 | 2  | 2  | 7  | 7   |
| 2    | Lincoln Park High School                         | 0                  | 0  | 69 | 0  | 0   |
| 2    | Lincoln Park High School                         | 22                 | 9  | 0  | 7  | 7   |
| 2    | Lincoln Park High School                         | 23                 | 14 | 2  | 80 | 80  |
| 2    | Paxton High School                               | 8                  | 2  | 18 | 40 | 40  |
| 2    | Pritzker School                                  | 0                  | 30 | 0  | 10 | 10  |
| 2    | Schubert School                                  | 20                 | 2  | 12 | 5  | 5   |
| 2    | Wells Academy High School                        | 2                  |    |    |    |     |
| 3    | Cooper School                                    | T                  | B  | D  |    |     |
| 3    | Crane Tech High School                           | 37                 | 0  | 0  | 7  | 7   |
| 3    | Dvorak Academy                                   | 43                 | 5  | 0  | 7  | 7   |
| 3    | Jefferson T. School                              | 33                 | 51 | 0  | 0  | 0   |
| 3    | Juarez High School                               | 10                 | 19 | 0  | 7  | 7   |
| 3    |  |                    |    |    |    |     |
| 4    | Curie Metro High School                          | 0                  | 0  | 76 | 0  | 0   |
| 4    | Curie Metro High School                          | 2                  | 0  | 69 | 6  | 6   |
| 4    | DuSable Campus                                   | 0                  | 23 | 4  | 2  | 2   |
| 4    | Farragut Academy                                 | 0                  | 0  | 69 | 0  | 0   |
| 4    | Paderewski School                                | 16                 | 9  | 2  | 10 | 10  |
| 4    |  |                    |    |    |    |     |
| 5    | Bradwell School                                  | 0                  | 55 | 1  | 9  | 9   |
| 5    | Englewood Technical                              | 0                  | 0  | 76 | 0  | 0   |
| 5    | Preparatory Academy (See<br>TEAM Englewood 8080) | 55                 | 0  | 0  | 6  | 6   |
| 5    | Gage Park High School                            | 1                  | 4  | 68 | 6  | 6   |
| 5    | Hope College Prep High School                    | 0                  | 0  | 76 | 0  | 0   |
| 5    | Kennedy High School                              |                    |    |    |    |     |

| REG. | SCHOOL                  | Affirmative Action |    |    |    | WBE |
|------|-------------------------|--------------------|----|----|----|-----|
|      |                         | AA                 | H  | A  |    |     |
| 5    | Kennedy High School     | 26                 | 8  | 0  | 0  | 7   |
| 5    | O'Toole School          | 0                  | 0  | 30 | 0  | 11  |
| 5    | Sexton School           | 17                 | 13 | 0  | 0  | 9   |
| 5    | Simeon High School      | 62                 | 0  | 0  | 0  | 5   |
|      |                         |                    |    |    |    |     |
| 6    | Carver Military Academy | 0                  | 0  | 76 | 0  | 0   |
| 6    | Curtis School           | 1                  | 27 | 3  | 8  | 8   |
| 6    | Haley, Alex School      | 0                  | 14 | 16 | 5  | 5   |
| 6    | Morgan Park High School | 5                  | 0  | 0  | 0  | 5   |
| 6    | Sutherland School       | 40                 | 0  | 0  | 19 | 19  |
| 6    | Washington High School  | 8                  | 0  | 17 | 0  | 0   |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**
**May Change Order Log  
Changes Under \$50,000 and 10% (Cumulatively)**
**APPENDIX B  
4/21/2011**

| School   | Project Num    | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC.      | COR# CO AMOUNT  | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON AMOUNT | % OF TIME EXTN |
|--|----------------|--------------|------------------|------|--|-----------------|---------------------------|--------------------------|-------------------------|----------------|----------------|
| Bethune School   | 2010-2661-ADA  | 1885070      | 10-0324-PR4      | 3    | GC Chicago Commercial Contractors, LLC Inc.  | 7 (\$13.261)    | \$0                       | \$447,379                | \$434,118               | -2.96%         | 0              |
| Description >> Credit for remaining project allowance.   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Reason >> Credit for remaining project allowance.  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Justification >> Discovered or Changed Conditions  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Bogan Technical High School  | 2010-46041-PLS | 2007879      | 10-0922-PR8      | 5    | GC F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 7 (\$654)       | \$12,710                  | \$785,000                | \$797,056               | 1.54%          | 0              |
| Description >> Provide manually operated shower systems in lieu of the electrically operated systems specified (infrared) Proposal should eliminate junction boxes, conduit and wiring associated with electrically operated system. |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Reason >> The specified system was an infrared (touchless) system. Since the showers are turned on by the PE instructors, an infrared system was not necessary.  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Justification >> Discovered or Changed Conditions  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Bronzeville Lighthouse   | 2007-3790-BLR  | 1678B12      | 09-0225-PR4      | 4    | GC Chicago Commercial Contractors, LLC CPS1  | 1019 \$10,752   | \$178,802                 | \$2,266,940              | \$2,456,494             | 8.36%          | 0              |
| Description >> Revised sequence of operation for AHU 1 and 2   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Reason >> The sequencing was never issued as an addendum during bidding.   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (AOR)  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Brown School   | 2009-2400-ADA  | 1893524      | 10-0428-PR8      | 3    | GC Chicago Commercial Contractors, LLC CPS1  | 1019 (\$20,590) | (\$19,484)                | \$1,155,497              | \$1,115,422             | -3.47%         | 0              |
| Description >> Credit remaining allowances in the contract   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Reason >> Credit remaining allowances in the contract  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Justification >> Owner Directed  |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Carpenter School   | 2010-22561-CSP | 1918B44      | 10-0526-PR3      | 2    | GC Miller                                    | 20 \$1,067      | \$16,065                  | \$1,554,900              | \$1,572,032             | 1.10%          | 0              |
| Description >> Provide pipe insulation for all exposed piping in locker rooms 2029 and 2031.   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Reason >> The contractor could not route as shown because of the existing structural conditions. An offset was needed.   |                |              |                  |      |  |                 |                           |                          |                         |                |                |
| Justification >> Discovered or Changed Conditions  |                |              |                  |      |  |                 |                           |                          |                         |                |                |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Under \$50,000 and 10% (Cumulatively)**

11-0525-PR5

APPENDIX B  
4/21/2011

| School  | Project Num     | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR | ARCHITECT OF REC.                        | COR # | CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON | % OF TIME EXTN |
|---|-----------------|--------------|------------------|------|--------------------|--|-------|-----------|---------------------------|--------------------------|-------------------------|---------|----------------|
| Cather School   | 2010-26021-CSP  | 1962953      | 10-0728-PR10     | 3    | MEC                | Wight/GSG Joint Venture                  | 5     | \$13,555  | \$0                       | \$912,742                | \$926,297               | 1,49%   | 0              |
| Description >> Additional abatement was needed in room 105 to facilitate in the concrete saw cutting.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The trenching of the floor was shown on the contract drawings; however it was not shown in the environmental manual for abatement. Asbestos VCT had to be removed prior to any concrete saw cutting.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Error/Omission (MEC)   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Paint exposed duct work and access panels in science lab.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> New rectangular duct work was installed in the science lab as exposed.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Error/Omission (AOR)   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Demo existing sinks and piping in rooms 105 & 217.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The sink removal was shown on the drawings for room 217, but not for room 105.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Permit Review  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Additional epoxy tops need to be ordered in order to rework the tops around an existing column and newly installed heating pipe.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The vent piping changed after permit review. WC had already ordered the epoxy tops prior to the review being completed.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Permit Review  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Permit revisions were issued after the work had been installed. Plumbing piping had to be torn out and redone.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> After the vent piping had been installed, the AOR made a field visit and directed the plumber to redo the piping based on changes from the permit review. The vent piping also had to be redone in order to conceal the vent piping in the epoxy backsplash and below the window. |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Permit Review  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> There are 3 feeders for the unit ventilators that are in the middle of the floor. These feeders need to be moved to the wall.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> After removing the unit ventilators, it was discovered that 3 additional feeders existed that needed to be relocated in order to remain active.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Discovered or Changed Conditions   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Wight Construction is requested to be reimbursed the manufacturer's roof inspection.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The existing roof was 2 years old and this project installed new roof top curbs. A manufacturer's representative was sent out to verify the existing warranty has been maintained.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Owner Directed   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Provide additional sign back plates on areas where signs were installed on the wire glass.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> Signage was shown on drawings to be mounted on the glass side light. This installed requires an additional panel on the back side to conceal the glue marks.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Discovered or Changed Conditions   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Description >> Install VCT in room 208 after asbestos VCT was abated.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The environmental manual showed to abate the entire VCT floor in room 208. AOR drawings did not show to remove the entire room of VCT rather showed removing the VCT in the closet area.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Error/Omission (MEC)   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Cather School   | 2010-26021-CSP  | 1962953      | 10-0728-PR10     | 3    | MEC                | Wight/GSG Joint Venture Inc.             | 6     | (\$636)   | \$0                       | \$912,742                | \$912,106               | -0.07%  | 0              |
| Description >> Credit for unused Project Allowance  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> Credit for unused Project Allowance   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Discovered or Changed Conditions   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Dumas School  | 2010-6690-ADA   | 1888104      | 10-0324-PR4      | 5    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc. Inc. | 1021  | \$9,786   | \$4,006                   | \$1,240,000              | \$1,253,792             | 1.11%   | 0              |
| Description >> Provide new 100amp 120/208 3 phase panel board   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> Existing panel boards did not have enough spare circuits to accommodate the new branch circuits.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Error/Omission (AOR)   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Dunbar High School  | 2010-53021-CAR1 | 1935150      | 10-0623-PR6      | 4    | GC                 | Friedler Construction Co.                | 1021  | \$4,000   | \$39,294                  | \$1,628,000              | \$1,671,294             | 2.66%   | 0              |
| Description >> Provide new conduit for light fixtures in storage rooms 122C, 122D, 124C, 124D. As per RFI #57.  |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Reason >> The light fixtures were called out to be reconnected to existing power feed. However the existing power feeds has to be demolished to allow for the new ceilings to be installed.   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |
| Justification >> Error/Omission (AOR)   |                 |              |                  |      |                    |  |       |           |                           |                          |                         |         |                |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log**

**APPENDIX B**

11-0525-PR5

4/21/2011

**Changes Under \$50,000 and 10% (Cumulatively)**

| School  | Project Num      | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR | ARCHITECT OF REC.                         | COR# CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON     | % OF TIME EXTN |   |
|---|------------------|--------------|------------------|------|--------------------|---|----------------|---------------------------|--------------------------|-------------------------|-------------|----------------|---|
| Dunbar High School  | 2010-53021-CAR-1 | 1935150      | 10-0623-PR6      | 4    | GC                 | Friedler Construction Co.                 | 1032           | \$3,474                   | \$39,294                 | \$1,628,000             | \$1,670,758 | 2.63%          | 0 |
| Description >> Additional electrical work at rooms 105, 115, 120, 124A to revise fan interlocking scope.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> The base scope was to interlock the new equipment installed by the project to the controls of the existing fans. However, the existing pneumatic controls don't work properly and the connections cannot be made. In order to allow proper operation of the equipment, switches that allow manual operation of the fans need to be installed. |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Dvorak Academy  | 2009-6760-MCR    | 176627       | 09-0722-PR6      | 3    | GC                 | Reliable & Associates Construction Co.    | 1035           | \$14,266                  | \$232,351                | \$2,495,988             | \$2,742,605 | 9.88%          | 0 |
| Description >> Provide wall and door at dead end corridor   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> The wall and door are need to comply with fire code for exceeding length of dead end corridor.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Code Change (Fire)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Field School  | 2006-3350-ADA    | 1557412      | 08-0723-PR6      | 1    | GC                 | Reliable & Associates Construction Co.    | 12R            | \$3,102                   | \$39,624                 | \$2,720,651             | \$2,763,377 | 1.57%          | 0 |
| Description >> Provide relay for 24 volt solenoid valve for the fire pump. Provide complete fire pump test per contract documents.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> The City of Chicago Fire Protection inspector has requested that the non-functioning existing sprinkler system be fixed. (Not part of original scope of work)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Code Change (Fire)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Hubbard High School   | 2010-46341-PLS   | 2007388      | 10-0922-PR8      | 5    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 10             | (\$2,550)                 | \$39,546                 | \$788,000               | \$824,996   | 4.69%          | 0 |
| Description >> Eliminate specified shower liner system  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> Revision was made during shop drawing review  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Error/Omission (AOR)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Hubbard High School   | 2010-46341-PLS   | 2007388      | 10-0922-PR8      | 5    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 16             | \$5,009                   | \$39,546                 | \$788,000               | \$832,554   | 5.65%          | 0 |
| Description >> Roof exhaust fan over Natatorium   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> The roof exhaust fan motor above the natatorium has stopped working. Fan is 3786 CFM  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Hubbard High School   | 2010-46341-PLS   | 2007388      | 10-0922-PR8      | 5    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 17             | \$5,000                   | \$39,546                 | \$788,000               | \$832,546   | 5.65%          | 0 |
| Description >> Surge tank return line scoping   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> There is possible blockage in the return lines for the surge tank. Condition was discovered during filling of pool. Scoping the lines will indicate if there is blockage and if so, if rodding is needed.   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Lane Tech High School   | 2010-46221-PLS   | 2007301      | 10-0922-PR8      | 1    | GC                 | Miller                                    |                |                           |                          |                         |             |                |   |
| Description >> Shot blast and epoxy (18) locker bases.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> Locker bases should have been included in the scope to complete the floor system.   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Error/Omission (AOR)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Lawndale Academy  | 2010-311161-DEM  | 2031094      | 10-1117-PR4      | 3    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 1001           | \$45,821                  | \$0                      | \$1,121,688             | \$1,167,509 | 4.09%          | 0 |
| Description >> scope modifications pursuant to permit review.   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> Scope changes were required by MOPD and CDOT during the permit review process.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Code Change (MOPD)   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Lawndale Academy  | 2010-311161-DEM  | 2031094      | 10-1117-PR4      | 3    | GC                 | F.H. Paschen S N Nielsen & Assoc., Inc.   | 1002           | (\$2,305)                 | \$0                      | \$1,121,688             | \$1,119,383 | -0.21%         | 0 |
| Description >> Delete alternate work from base scope for the downspout and connection to storm sewer.   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Reason >> Scope was changed after the project was awarded pursuant to modifications to the vestibule entrance.  |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                  |              |                  |      |                    |   |                |                           |                          |                         |             |                |   |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Under \$50,000 and 10% (Cumulatively)**

11-0525-PR5

**APPENDIX B**

4/21/2011

| School  | Project Num.   | Contract Num. | Board Report REG | TYPE | GENERAL CONTRACTOR | ARCHITECT OF REC.                         | COR # CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON AMOUNT | % OF TIME EXTN |
|---|----------------|---------------|------------------|------|--------------------|---|-----------------|---------------------------|--------------------------|-------------------------|----------------|----------------|
| Lincoln Park High School  | 2010-46321-PLS | 2007898       | 10-0922-PR8      | 2    | GC                 | Brown & Momen Inc.                        | 3               | \$19,081                  | \$43,829                 | \$848,000               | \$910,910      | 7.42%          |
| Description >> Skim coat entire pool ceiling and beams with integral color in an acrylic finish.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Scrape, patch, and paint is currently scoped. This will not provide a smooth finish and will not last in a humid environment. An acrylic finish product will do both.   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (DM)  | 2008-4380-ADA  | 1872389       | 10-0324-PR4      | 2    | GC                 | Brown & Momen Inc.                        | 012             | (\$1,000)                 | \$8,777                  | \$1,078,702             | \$1,086,479    | 0.72%          |
| Description >> CREDIT: Provide credit for 4 retrofit tree grates; Remove excess concrete debris from pits. Include abandoned horizontal and vertical piping.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Per the Dept of Landscaping, the tree grates were no longer required. Discovered debris and conflicts with existing site elements while implementing the work.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Discovered or Changed Conditions   | 2010-24301-BLR | 1902993       | 10-0326-PR3      | 5    | GC                 | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 15              | \$1,089                   | \$83,047                 | \$1,435,000             | \$1,519,136    | 5.86%          |
| Description >> Provide new combination HOA starters for EF-1 and EF-2.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> The existing electrical drawings indicated the existing starters were to remain for EF-1 and EF-2. These starters did not exist. Thus, they had to be replaced.   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (AOR)   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL 13          | \$5,831                   | \$1,728,466              | \$27,189,127            | \$28,923,424   | 6.38%          |
| Description >> Replace existing broken 10" day storm sewer line with new 10"ESVCP storm sewer line per City of Chicago requirements. All existing invert, slopes and connections to be maintained.                              |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Sewer line discovered to be broken.   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Discovered or Changed Conditions   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL139          | \$5,307                   | \$1,728,466              | \$27,189,127            | \$28,922,900   | 6.38%          |
| Mather High School  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Description >> Provide hat channels and tile backer board at east wall of toilet stall in Toilet Room 212B. Provide new 4" X 4" ceramic wall tile to match existing tile. Reinstall all grab bars and toilet tissue dispensers. |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Scope specified to relocate water closet to meet ADA requirements, but water closet could not be located at this location due to existing main vent line inside pipe chase.   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (AOR)   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL 140         | \$1,516                   | \$1,728,466              | \$27,189,127            | \$28,919,109   | 6.36%          |
| Description >> Provide additional wire-mesh partition sections above existing lockers at Boys Locker Room (26 ft).  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Requested by School to secure team locker area after multiple thefts have occurred.   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Owner Directed   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL143          | \$12,213                  | \$1,728,466              | \$27,189,127            | \$28,929,906   | 6.40%          |
| Mather High School  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Description >> Replace supply fan motor VFD specified with new 208v/3 phase VFD at AHU-11.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Incorrect voltage specified for new VFD.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (AOR)   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL144          | \$2,784                   | \$1,728,466              | \$27,189,127            | \$28,920,377   | 6.37%          |
| Mather High School  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Description >> In lieu of detail indicated in Contract Documents, provide additional wood blocking, plywood sheathing, insulation and aluminum cover at Music Wing roof.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> Existing roof drains in this confined area could not be modified to accommodate specified roof detail.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Error/Omission (AOR)   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL146          | \$3,498                   | \$1,728,466              | \$27,189,127            | \$28,921,091   | 6.37%          |
| Mather High School  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Description >> At Cafeteria 437 prep, patch and paint entire existing ceiling.  |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Reason >> When walls were patched and painted as part of base scope ceilings needed to be done to match the finish of the walls   |                |               |                  |      |                    |   |                 |                           |                          |                         |                |                |
| Justification >> Owner Directed   | 2007-1480-CSP  | 1726765       | 09-0624-PR8      | 1    | GC                 | Tyler Lane Construction, Inc.             | BUL17           | \$7,583                   | \$1,728,466              | \$27,189,127            | \$28,925,176   | 6.39%          |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Under \$50,000 and 10% (Cumulatively)**

11-0525-PR5  
APPENDIX B  
4/21/2011

| School  | Project Num   | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC. | COR # CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT % OF CON EXTN    |
|---|---------------|--------------|------------------|------|---|-----------------|---------------------------|--------------------------|-------------------------|----------------------|
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL27           | \$3,816                   | \$1,728,466              | \$27,189,127            | \$28,921,409 6.37% 0 |
| Description >> Existing guardrail at Natatorium balcony and provide new stainless steel guardrail system. Patch and paint existing surfaces to match adjacent surfaces.                                     |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Existing guardrail is unsafe and needs to be replaced.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Discovered or Changed Conditions   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL52           | \$5,008                   | \$1,728,466              | \$27,189,127            | \$28,922,601 6.38% 0 |
| Description >> Provide VCT flooring and vinyl base at Greenhouse 421.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Concrete documents specified sealed concrete floor. VCT direction of owner walk-through.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Owner Directed   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL53           | \$501                     | \$1,728,466              | \$27,189,127            | \$28,918,094 6.36% 0 |
| Description >> Modify new Closet 604C to accommodate electrical panels.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Electrical panels could not fit in closet as shown on Contract Documents.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Error/Omission (AOE)   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL54           | \$1,992                   | \$1,728,466              | \$27,189,127            | \$28,919,584 6.36% 0 |
| Description >> Provide painted drywall ceiling window pocket at Rooms 603 and 604D per Detail JS/A6.30.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Soffit and window pocket not shown on Contract Documents.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Error/Omission (AOE)   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL55           | \$6,144                   | \$1,728,466              | \$27,189,127            | \$28,923,737 6.38% 0 |
| Description >> Relocate existing wall grilles (return air transfer duct to corridor) at Rooms 509, 505, 503, 501, 219, 432, 429 and 712.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Incorrect location shown on Contract Documents.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Error/Omission (AOE)   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL56           | \$5,179                   | \$1,728,466              | \$27,189,127            | \$28,922,772 6.38% 0 |
| Description >> Provide painted drywall soffit to endclose existing insulated pipe in Art Room 215.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Soffit created to give room a finished look.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Owner Directed   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL57           | \$1,970                   | \$1,728,466              | \$27,189,127            | \$28,919,563 6.36% 0 |
| Description >> Increase size of specified painted drywall soffits for the new VAV installation in Rooms 432, 501, 218, 307, 303.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Shifted location of VAV's due to discovered field interferences.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Discovered or Changed Conditions   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.        | BUL58           | \$1,478                   | \$1,728,466              | \$27,189,127            | \$28,919,071 6.36% 0 |
| Description >> Provide additional painted drywall soffit in Room 712 to accommodate revised location of VAV.  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> VAV location revised due to discovered field interferences.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Discovered or Changed Conditions   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction Inc          | BUL59           | \$4,420                   | \$1,728,466              | \$27,189,127            | \$28,922,013 6.37% 0 |
| Description >> Replace water damaged ceiling tile in comdors. Drywall, tape and paint around existing door frame opening at Doors 250 1 and 250 2. provide painted wood trim at location of security gates. |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Not part of base scope in Contract Documents. Work to be completed to provide overall finished look of space.   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Discovered or Changed Conditions   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Mather High School  | 2007-1480-CSP | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction Inc          | BUL60           | \$2,250                   | \$1,728,466              | \$27,189,127            | \$28,919,843 6.37% 0 |
| Description >> Repair existing drywall at Stair ST-1 damaged by water pipe leak above second floor janitors Closet  |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Reason >> Leak due to overflow of drain in janitor sink above   |               |              |                  |      |   |                 |                           |                          |                         |                      |
| Justification >> Discovered or Changed Conditions   |               |              |                  |      |   |                 |                           |                          |                         |                      |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log**

11-0525-PR5

**APPENDIX B**

**Changes Under \$50,000 and 10% (Cumulatively)**

| School  | Project Num    | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC.      | COR# CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON % OF TIME EXTRN |
|---|----------------|--------------|------------------|------|--|----------------|---------------------------|--------------------------|-------------------------|-------------------------|
| Mather High School  | 2007-1480-CSP  | 1726765      | 09-0624-PR8      | 1    | GC Tyler Lane Construction, Inc.             | BUL61          | \$7,762                   | \$1,728,466              | \$27,189,127            | \$28,925,355 6.39% 0    |
| Description >> Provide painted drywall chase box outs for new fin tube in Rooms 417, 419, 437, 439, 509. Provide access panel at each box out.  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Required when fin tube scope was added to project. Not included in previous mechanical change order to add fin tubes.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Mays Academy  | 2009-150-ADA   | 1847884      | 10-0127-PR1      | 5    | GC Reliable & Associates Construction Co. C1 | (\$54,730)     | \$0                       | \$696,658                | \$641,938               | -7.86% 0                |
| Description >> CREDIT Unused allowances   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> This portion of the allowance money was not used during the project   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Other  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Description >> CREDIT For painting and sealing SGT in lieu of installing a custom manufactured exact color SGT  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Painting and sealing the missed match SGT in lieu of providing custom matched SGT was done because of a long lead time and difficulty in achieving an exact match of existing SGT.(The install, credit and five year guarantee of work was approved by CPS) |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Owner Directed   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Phillips High School  | 2010-46261-CSP | 1959521      | 10-0728-PR10     | 4    | GC Chicago Commercial Contractors, LLC       | 08             | \$9,648                   | \$190,537                | \$3,191,901             | \$3,392,086 6.27% 0     |
| Description >> In Room 121H, at area of wall removal, furr out small section of wall to cover existing discovered chase. Paint new GWB to match ceiling. Provide two (2) corner guards to 6' above the floor. Install new CT to match existing base.                  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Per MOPD, we need to expand room to obtain necessary turning radius clearances.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Code Change (MOPD)   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Description >> In Rooms 123A, 223A and 323A, relocate existing fire alarm devices from face of existing masonry wall to face of new drywall assembly. Return to service and test.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Existing devices need to be relocated to install new walls.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Error/Omission (AOR)   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Description >> Provide additional, custom floor tile (VCT and CT) in typical classrooms, water closets and a "VP" logo in the computer classroom.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> School requested changes after project was awarded to GC.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Owner Directed   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Phillips High School  | 2010-46261-CSP | 1959521      | 10-0728-PR10     | 4    | GC Chicago Commercial Contractors, LLC       | 09             | \$2,108                   | \$190,537                | \$3,191,901             | \$3,384,547 6.04% 0     |
| Description >> Provide two (2) new oak sink bases in Rooms 301 & 304.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> New sinks shown on drawings, however, no new bases shown. Need bases to install new sinks.  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Error/Omission (AOR)   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Description >> In Boys Water Closet 001A, furr out wall to accommodate new plumbing lines for sink.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Upon demolition of existing wall to install new plumbing lines, we discovered an existing concrete foundation/structure that cannot be removed or relocated. Need to bump-out plumbing lines to install. Need to conceal lines by furring out the wall.     |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Schurz High School  | 2006-1530-BLR  | 1909837      | 10-0526-PR3      | 1    | GC F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 40             | \$13,370                  | \$294,650                | \$10,445,000            | \$10,753,020 2.95% 0    |
| Description >> Additional ductwork for RF-3A and RF-3B.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Additional ductwork required due to field conditions.   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |  |                |                           |                          |                         |                         |
| Schurz High School  | 2006-1530-BLR  | 1909837      | 10-0526-PR3      | 1    | GC F H Paschen S.N. Nielsen & Assoc., Inc.   | 41             | \$18,810                  | \$294,650                | \$10,445,000            | \$10,758,460 3.00% 0    |
| Description >> Drain pan above domestic water pump. AHU belt guards for AHU 2,6 & 7. Provide and install (9) TDC metal panels.  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Reason >> Due to leaking roof, resheaving and revisions to pulley required larger belt guards.  |                |              |                  |      |  |                |                           |                          |                         |                         |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |  |                |                           |                          |                         |                         |

CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS

## **May Change Order Log**

### **Changes Under \$50,000 and 10% (Cumulatively)**

11-0525-PR5

**APPENDIX B**

**4/21/2011**

| School   | Project Num    | Contract Num | Board Report REG | Type | GENERAL CONTRACTOR<br>ARCHITECT OF REC.         | COR # CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON % OF TIME EXTN |
|--|----------------|--------------|------------------|------|---|-----------------|---------------------------|--------------------------|-------------------------|------------------------|
| Schurz High School   | 2006-1530-BLR  | 1905837      | 10-0526-PR3      | 1    | GC<br>F.H. Paschen, S.N. Nielsen & Assoc., Inc. | \$4,464         | \$294,650                 | \$10,445,000             | \$10,744,114            | 2.86% 0                |
| Description >> Add steam fintube to room 263.<br>Reason >> This room requires supplemental heat.<br>Justification >> Owner Directed  |                |              |                  |      |   |                 |                           |                          |                         |                        |
| Simeon High School   | 2010-53061-PLS | 2007894      | 10-0922-PR8      | 5    | GC<br>Friedler Construction Co.                 | 14              | \$1,282                   | \$28,149                 | \$617,310               | \$646,740 4.77% 0      |
| Description >> Provide new flexible shower hose spray at existing accessible stall and grab bar revision<br>Reason >> Original bars specified are in conflict with existing flush valves; shower heads not originally scoped and need to be replaced.<br>Justification >> Error/Omission (AOR)                 |                |              |                  |      |   |                 |                           |                          |                         |                        |
| Simeon High School   | 2010-53061-PLS | 2007894      | 10-0922-PR8      | 5    | GC<br>Friedler Construction Co.                 | 15              | (\$5,198)                 | \$28,149                 | \$617,310               | \$640,261 3.72% 0      |
| Description >> Provide labor credit for installation of heating coil (Bulletin 7) and turn coil over to CPS<br>Reason >> AHU replacement is not occurring due to dehumidification project - AHU already ordered so credit will be for labor install only.<br>Justification >> Discovered or Changed Conditions |                |              |                  |      |   |                 |                           |                          |                         |                        |
| TEAM Englewood Comm Academy  | 2010-46351-PLS | 2007893      | 10-0922-PR8      | 5    | GC<br>Friedler Construction Co.                 | 7               | \$5,851                   | \$21                     | \$421,188               | \$427,060 1.39% 0      |
| Description >> Revise door frame and edge material from aluminum to stainless steel at 5 doors.<br>Reason >> Revision to standards to stainless steel doors<br>Justification >> Owner Directed   |                |              |                  |      |   |                 |                           |                          |                         |                        |
| <b>Total Change Orders:</b>  |                |              |                  |      |   |                 |                           |                          |                         | <b>\$171,089</b>       |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Over \$50,000 or 10% (Cumulatively)**

**APPENDIX C  
4/21/2011**

| School  | Project Num    | Contract Num | Board Report REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC.   | COR # CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON     | % OF TIME EXTN |   |
|---|----------------|--------------|------------------|------|---|-----------------|---------------------------|--------------------------|-------------------------|-------------|----------------|---|
| Amundsen High School  | 2010-46031-ADA | 1893516      | 10-0428-PR8      | 1    | GC Miller                                 | 55              | \$10,000                  | \$649,849                | \$2,539,000             | \$3,198,849 | 25.99%         | 0 |
| Description >> Furnish and install exhaust fan, ductwork, grilles, louvers and power for exhausting Teacher Toilet #185 and Unisex Toilet #285.   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> Existing exhaust grille is not connected to any duct and there is no exhaust fan. The replacement of the existing grilles is part of base scope and has been completed.   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Amundsen High School  | 2010-46031-ADA | 1893516      | 10-0428-PR8      | 1    | GC Miller                                 | 57              | \$5,622                   | \$649,849                | \$2,539,000             | \$3,194,471 | 25.82%         | 0 |
| Description >> Emergency repair of the hot water storage tank.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> At the bottom of the hot water storage tank a major leak developed due to defonation that needed to be repaired. School was without hot water until it was repaired.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Owner Directed   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Amundsen High School  | 2010-46031-ADA | 1893516      | 10-0428-PR8      | 1    | GC Miller                                 | 59              | \$41,283                  | \$649,849                | \$2,539,000             | \$3,230,132 | 27.22%         | 0 |
| Description >> Furnish and install new electrical building grounding system.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> This scope is required and was missed on Bulletin #32.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Error/Omission (AOR)   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Amundsen High School  | 2010-46031-ADA | 1893516      | 10-0428-PR8      | 1    | GC Miller                                 | 61R             | \$6,822                   | \$649,849                | \$2,539,000             | \$3,195,671 | 25.86%         | 0 |
| Description >> Remove existing recessed stage floor lighting, wiring and access doors. Install new hardwood flooring to match existing.   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> 2. Furnish and install new hardwood audio equipment storage cabinet in location of existing/ demolished cabinet.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| 17  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Lighting and access doors pose a tripping hazard due to work per Bulletin #45.   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Due to the poor conditions of the existing trap door the location per Bulletin #45 can not be used.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Owner Directed   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Blaine School   | 2005-2300-BLR  | 1300448      | 07-0523-PR5      | 1    | GC Reliable & Associates Construction Co. | 32              | \$26,435                  | \$329,843                | \$2,104,024             | \$2,460,302 | 16.93%         | 0 |
| Description >> Work overtime for 8 weeks to complete the heating system.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> Principal will not allow contractor to work in the building while there are students present. Due to an after school paid program the contractor cannot start until 6:00 PM making this overtime and not second shift per union agreements. |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Discovered or Changed Conditions   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Carver Military Academy   | 2010-46381-PLS | 2007911      | 10-0922-PR8      | 6    | GC Miller                                 | 15r             | \$38,000                  | \$44,911                 | \$589,000               | \$67,911    | 14.08%         | 0 |
| Description >> Re-grout the pool  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> recommendation by pool consultant and aor   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Error/Omission (DM)  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Chase School  | 2010-22701-ADA | 1893520      | 10-0428-PR8      | 2    | GC Chicago Commercial Contractors, LLC    | 27              | \$91,920                  | \$167,524                | \$1,563,024             | \$1,822,468 | 16.60%         | 0 |
| Description >> Remove stage lift in Gym and reconfigure lift in adjacent Classroom.   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> Owners request for one lift to be removed and one lift in classroom to be reconfigured  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Owner Directed   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Chase School  | 2010-22701-ADA | 1893520      | 10-0428-PR8      | 2    | GC Chicago Commercial Contractors LLC     | 28              | \$7,500                   | \$167,524                | \$1,563,024             | \$1,738,048 | 11.20%         | 0 |
| Description >> Remove ACM from piping in the vicinity of water heater.  |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Reason >> The ACM at nearby piping needed to be removed in order to change the valve that would allow to shut down the plumbing and do a tie in   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |
| Justification >> Owner Directed   |                |              |                  |      |   |                 |                           |                          |                         |             |                |   |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Over \$50,000 or 10% (Cumulatively)**

11-0525-PR5

APPENDIX C  
4/21/2011

| School   | Project Num   | Contract Num | Board Report | REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC.   | COR # | CO AMOUNT | PREVIOUS APPROVED<br>CHANGES | ORIGINAL CONTRACT<br>AMOUNT | REVISED CONTRACT<br>AMOUNT | TOT % OF CON | TIME EXTN |
|--|---|--------------|--------------|-----|------|---|-------|-----------|------------------------------|-----------------------------|----------------------------|--------------|-----------|
| Curtis School  | 2008-3160-BLR   | 1833141      | 09-1123-PR6  | 6   | GC   | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 27    | \$7,468   | \$224,234                    | \$1,981,000                 | \$2,212,702                | 11.70%       | 0         |
| Description >> Install 2 new 2/3 steam valves and switch the existing 2/3 steam valves the 1/3 steam valves location |   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | The hot decks at the school could not maintain the set point and it was discovered that the EOR approved values that were to small and to correct the problem the values have to be switch to bigger values in order to reach the set point for the hot deck  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (AOR)  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Farragut Academy   | 2010-53091-PLS  | 2007886      | 10-0922-PR8  | 4   | GC   | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 1032  | \$5,860   | \$365,350                    | \$1,113,000                 | \$1,485,210                | 33.44%       | 0         |
| Description >>   | Provide 5 new locker to match height of lockers and move all ADA lockers to one location.   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | The delivered lockers are taller than the general lockers. The additional lockers will make the layout more uniform.  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (AOR)  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Farren School (Now Attucks School)   | 2009-3300-ADA   | 1817020      | 09-1028-PR3  | 4   | GC   | Chicago Commercial Contractors, LLC       | CR3   | (\$724)   | \$107,052                    | \$960,012                   | \$1,066,340                | 11.08%       | 0         |
| Description >>   | Credit unused allowances  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | The job is complete.  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Owner Directed  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Gage Park High School  | 2010-46141-PLS  | 2007890      | 10-0922-PR8  | 5   | GC   | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 28    | \$6,300   | \$253,089                    | \$697,000                   | \$956,389                  | 37.22%       | 0         |
| Description >>   | Emergency lighting replacement - boys and girls locker rooms  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | Upon installation of new Emergency Exit signs, some do not work - testing and fixing of lights / circuits   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Discovered or Changed Conditions  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Gage Park High School  | 2010-46141-PLS  | 2007890      | 10-0922-PR8  | 5   | GC   | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | 29    | \$833     | \$253,089                    | \$697,000                   | \$950,922                  | 36.43%       | 0         |
| Description >>   | Reinforcement for partition panel at entrance to boys locker room   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | After installation of the new privacy screen, it was evident that the bracing included allowed too much deflection.   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (AOR)  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Hyde Park Academy  | 2010-46171-PLS  | 2007895      | 10-0922-PR8  | 5   | GC   | Friedler Construction Co.                 | 13    | \$9,413   | \$26,647                     | \$1,000,302                 | \$1,271,362                | 27.10%       | 0         |
| Description >>   | Change location for specific new panelboards and transformer from Pool Equipment room to Corridor 114. Provide drywall (impact resistant) on metal stud chase wall from floor to 6 inches above ceiling grid; paint new wall; Recess mount new panelboards and mount new transformer on platform above ceiling. |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | Pool Equipment room cannot be used for panelboards / transformers per electrical inspector.   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (AOR)  |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Hyde Park Academy  | 2010-46171-PLS  | 2007895      | 10-0922-PR8  | 5   | GC   | Friedler Construction Co.                 | 7a    | \$38,305  | \$26,647                     | \$1,000,302                 | \$1,300,255                | 29.99%       | 0         |
| Description >>   | ADDITIONAL DOLLARS TO 7 (Previously approved 7 did not include all of the floor and associated prep) Reflects credit for Epoxy and concrete underlayment from original bulletin 7   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | The extent of tile patching required by underground plumbing will not result in an uniform floor finish acceptable to CPS. The amount previously submitted in 7A did not include all of the flooring or floor prep. This is for the balance of the flooring and the entire floor prep.                          |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (IM)   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Kennedy High School  | 2010-46201-PLS  | 2008374      | 10-0922-PR8  | 5   | GC   | F.H. Paschen S.N. Nielsen & Assoc., Inc.  | 20    | \$11,126  | \$109,135                    | \$805,000                   | \$925,260                  | 14.94%       | 0         |
| Description >>   | Floor Drains at Boys Locker and Shower Curb at Girls Shower   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Reason >>  | Water is being carried outside of the shower rooms To fix Girls Shower Room, concrete curbs were removed and replaced with a 1/2" high curb Drains were added to the Boys Locker and Boys Shower.   |              |              |     |      |   |       |           |                              |                             |                            |              |           |
| Justification >>   | Error/Omission (AOR)  |              |              |     |      |   |       |           |                              |                             |                            |              |           |

**CHICAGO PUBLIC SCHOOLS  
DEPARTMENT OF OPERATIONS**

**May Change Order Log  
Changes Over \$50,000 or 10% (Cumulatively)**

11-0525-PR5

APPENDIX C  
4/21/2011

| School  | Project Num    | Contract Num | Board Report | REG | TYPE | GENERAL CONTRACTOR<br>ARCHITECT OF REC.   | COR # CO AMOUNT | PREVIOUS APPROVED CHANGES | ORIGINAL CONTRACT AMOUNT | REVISED CONTRACT AMOUNT | TOT CON      | % OF TIME EXTN |        |   |
|---|----------------|--------------|--------------|-----|------|---|-----------------|---------------------------|--------------------------|-------------------------|--------------|----------------|--------|---|
| Kennedy High School   | 2010-46201-PLS | 2008374      | 10-0922-PR8  | 5   | GC   | F.H. Paschen, S.N. Nielsen & Assoc., Inc. | \$109,337       | \$109,135                 | \$805,000                | \$917,472               | 13.97%       | 0              |        |   |
| Description >> Surge tanks<br>Reason >> Per IDPH, the surge tank was revised from a 900 gallon tank to a 957 tank (Revision missed in Bulletin 001RR).<br>Justification >> Error/Omission (AOR)   | 2010-46221-PLS | 2007901      | 10-0922-PR8  | 1   | GC   | Miller                                    |                 | 24                        | \$10,595                 | \$81,587                | \$890,000    | \$982,182      | 10.36% | 0 |
| Lane Tech High School   |                |              |              |     |      |   |                 |                           |                          |                         |              |                |        |   |
| Description >> Install 3M Safety-Walk Slip resistant tape at all treads on (4) bleacher stairways.<br>Reason >> School has indicated that current slip resistant product is not sufficient<br>Justification >> Owner Directed   | 2007-1480-CS-P | 1726765      | 09-0624-PR8  | 1   | GC   | Tyler Lane Construction, Inc.             | BUL115          | \$85,967                  | \$1,728,466              | \$27,189,127            | \$29,003,560 | 6.67%          | 0      |   |
| Mather High School  |                |              |              |     |      |   |                 |                           |                          |                         |              |                |        |   |
| Description >> Provide replacement drywall at ceiling and painting of Stairwell 1 and 4, paint exterior canopy, paint existing wiremold in classrooms, paint Lobby 601 columns, paint Cafeteria north wall. Patch and repaint entire teaching wall in each classroom following removal of wiremold and tv brackets.<br>Reason >> Areas to be painted directed by CPS at walk-thru.<br>Justification >> Owner Directed | 2007-1480-CS-P | 1726765      | 09-0624-PR8  | 1   | GC   | Tyler Lane Construction, Inc.             | BUL90           | \$65,821                  | \$1,728,466              | \$27,189,127            | \$28,983,413 | 6.60%          | 0      |   |
| Mollison School   |                |              |              |     |      |   |                 |                           |                          |                         |              |                |        |   |
| Description >> Various door and hardware revisions per Bulletin 90 (refer to attached).<br>Reason >> Revisions to doors based on scope changes and programmatic changes of school.<br>Justification >> Owner Directed   | 2009-6950-ADA  | 1833084      | 09-1123-PR6  | 4   | GC   | Chicago Commercial Contractors, LLC       | 1020            | (\$1,471)                 | \$138,594                | \$863,099               | \$1,000,222  | 15.89%         | 0      |   |
| Schurz High School  |                |              |              |     |      |   |                 |                           |                          |                         |              |                |        |   |
| Description >> Credit for Assisted Listening Device.<br>Reason >> The school does not have an existing PA device. The equipment is therefore not compatible.<br>Justification >> Discovered or Changed Conditions   | 2010-46281-ADA | 1909854      | 10-0428-PR8  | 1   | GC   | Chicago Commercial Contractors, LLC       | 86              | \$3,500                   | \$36,1,804               | \$3,584,258             | \$3,949,562  | 10.19%         | 0      |   |
| Washington High School  |                |              |              |     |      |   |                 |                           |                          |                         |              |                |        |   |
| Description >> Provide posts for exterior signs.<br>Reason >> Contract documents indicated signs but no post.<br>Justification >> Error/Omission (AOR)  | 2010-46331-PLS | 2007912      | 10-0922-PR8  | 6   | GC   | Miller                                    |                 | 12                        | \$29,856                 | \$51,406                | \$405,000    | \$486,262      | 20.06% | 0 |

**Total Change Orders:** **\$503,766**